



Date : 08/12/2012	نموذج تفتيش الشاحنات		
Truck Route From:	Truck Plate No.:	Type Of Truck	نوع الشاحنة:
ADDAF 2A	46812AD	Scania	
Truck Route To/ VIA:	Emp. No/ Third party Co:	Driver Name:	اسم السائق:
UAS	100146	Nawaf Muhannad	

All outbound vehicles leaving the facility need to be inspected by the security and a seven point vehicle inspection check needs to be carried out as per the TAPA best practice: These checks is to ensure that there is no damage to the vehicle that will lead to a theft and to ensure that the vehicles is secure with the necessary security seals. The 7 points covers the whole of the vehicle.

جميع السيارات المغادرة من الموقع لابد من تفتيشها من قبل الامن ويوجد سبع نقاط تتحقق ان تتحقق وفقاً لمتطلبات تابا هذه المتطلبات هو لضمان بانه لا يوجد هناك اي خلل على المركبة وضمان بان المركبة مؤمنة باتفاق امنية مرفقة، 7 نقاط تتحقق كامل المركبة:

1. من الامام



2. من اليسار



3. من اليمين

4. من فوق/ السقف

5. داخل وخارج الابواب

6. Locking Mechanism

7. Outside/Under carriage



Security Findings:

*Normal Condition*

ملاحظات:

Vehicle Security Seal No.: رقم الاقلام الامني: 8919711, 8919712	Random Cargo Checks Carried Out التفتيش العشوائي للحمولة Yes <input type="checkbox"/> No <input type="checkbox"/>	Checks on HV items Carried Out التفتيش على المواد عالية القيمة Yes <input type="checkbox"/> No <input type="checkbox"/>
HV Items Sealed: المواد عالية القيمة مؤمنة باتفاق امني : Yes <input type="checkbox"/> No <input type="checkbox"/>	What was checked? <i>7 points checked</i>	
Security Inspection Officer: <i>Amos</i>	Emp# <i>1010074</i>	Signature: 
Reviewed by Security Executive: <i>ALAA</i>	Emp# <i>81189</i>	Signature: 